

September 13, 2022

DVP-220038

Air Pollution Control Officer

Attention: Mr. Jack Cheng, AQAC Supervisor

South Coast Air Quality Management District

21865 E. Copley Drive

Diamond Bar, CA 91765-4182

Subject:

September 10, 2022, NOx ppm @ 3% O2 3-Hr Rolling Exceedance

SCAQMD FILE # 100154

Permit No. CB-ROP 05-01

NSR 4-4-11; SE 87-01

Dear Mr. Cheng:

Per our Title V permit I am attaching the Form 500-N for the NOx ppm @ 3% O2 3-Hr Rolling Average Exceedance Desert View Power incurred on September 10, 2022 during a malfunction with the CEM.

Please call if you have any questions or comments. I can be reached at (760) 262-1644.

Sincerely,

Kevin LaWrence

Plant Manager Desert View Power

Page 2

encl

cc:

Enforcement and Compliance Assurance Division
U.S. Environmental Protection Agency
75 Hawthorne Street
San Francisco, California 94105-3901

Chief, Industrial Strategies Division
California Air Resources Board
P.O. Box 2815
Sacramento, CA 95814

South Coast Air Quality Management District

Form 500-N

Title V - Deviations, Emergencies & Breakdowns

*This written report is in addition to requirements to verbally report certain types of incidents. Verbal reports may be made by calling AQMD at 1-800-288-7664 (1-800-CUT-SMOG) or AQMD enforcement personnel.

Mail To: SCAQMD P.O. Box 4941 Diamond Bar, CA 91765-0941

> Tel: (909) 396-3385 www.aqmd.gov

d. Caribb. Marca (Ousings)	Information		0 11 (14.0	AN SOM PO VCCA AND CA N		<u> </u>		
7	Name of Operator That Appears O	Valid AC AQMD):	IMD Facility ID (Availa		ivoice Issue			
Desert View Pov	ver		,		100154			
. Address:	62-300 Gene Welmas	Dr.						
(where incident occurred)		Street Address						
	Mecca			CA	92254			
	_	City		State	Zip			
Mailing Address: (if different from Item 3)	Same as above	Street Address						
(ii dilleterit itolii itelii o)	Same as above	Street Address						
	Jaille as above	City		State	Zip			
Provide the name, title, a	and phone number of the person	to contact for further information:			- Cap			
D	oug Fritsch	Operations Manag	ger	(760) 262-1682			
	Name	Title			Phone #	***************************************		
ection II - Reporting	of Breakdowns, Deviation	s, and Emergencies						
This written notification i	s to report a(n):							
Type of Incident		Verbal Report Due*	V	/ritten Report Due				
a. Emergency under	Rule 3002(g)	Within 1 hour of discovery	Within 2 working days from when the emission limit was exceeded.					
b. 🗵 Breakdown under:				For Rules 430 & 2004 -	Within 7 calendar of	lays after		
Rule 430 (Non	-RECLAIM)	For Rules 430 & 2004 - Within 1 hour of discovery.		oreakdown is corrected start of the breakdown,				
Rule 2004 (RE	CLAIM)	·	ģ	granted.				
Rule 218 (Non See Rule 218	-RECLAIM) (f)(3)]	For Rule 218 – Within 24 hours or next by day for failure/shutdown exceeding 24 ho	For Rule 218 - With required semi-annual reports.					
c. Deviation with exce [See Title V Permit,	ss emissions Section K, Condition No. 22B]	Within 72 hours of discovery of the deviat shorter reporting period if required by an applicable State or Federal Regulation.	tion or V	Within 14 days of discov	very of the deviation	1 ,		
d. Other Deviation [See Title V Permit,	Section K, Condition Nos. 22D & 2	None 3]	With required semi-annual monitoring reports.					
ha inaideat was first disa	overed by: Joe Pedroza		09	9/10/2022	05:10	₩ АВЛ		
iia iiicinaiif kas met oiec	overeu by.	Name v	n	Date	Time	* AM		
ha incident was first renn	rted by: Left message on	recorded line	n 09	9/10/2022	05:13	AM		
	Nam	e of AQMD Staff Person	** a	Date	Time	PM		
Via Phone In Person		Natification N	umber (Ren	uired): 715572				
hen did the incident actus	ally occur? 09/10/20:					***************************************		
ueu dia fua incident actu:	Date	Time PM						
Received By:	**************************************	Assigned By:	***************************************	Inspector:	***************************************			
Date/Time Received:	***************************************	Date/Time Assigned:	~~~~	Date/Time Receiv	ved Assignment	******************************		
Date Delivered To Team	u:	Date Reviewed Inspector Report:	Date Inspected Facility:					
Team:	Sector:	Breakdown/Deviation Notification No.	Date Completed Report:					
Recommended Action:	Cancel Notification Gr	ant Relief Issue NOV No		Other:				
Final Action:	Cancel Notification Gr	ant Relief Issue NOV No		Other:				

5. Has the incident stopped?	a. @ Yes, on:	***************************************		06:00	· AM	b. ⊂ No	
		Date		Time	← PM		
6. What was the total duration	of the incident?		·····	03			
		Days		Hours			
For equipment with an opera when was the end of the ope	ating cycle, as defin- erating cycle during	ed in Rule 430 (b)(3)(A), which the incident occurred	,0	9/10/2022 Date		05:59 Time	— (* Al
Describe the incident and id- equipment and attach addition Loss of stack flow due	onal pages as neces	ssary.		**		en available) of the a	ffected
 The incident may have result a. Violation of Permit Con 	CB	-ROP 05-01					
b. Violation of AQMD Rule	3(8).						
10. What was the probable cause			cessary	***************************************			~~~~
Stack flow indication of data. This caused the	lropped due to a NOx ppm @ 39	a bad O ring gasket or % O2 to increase beca	the CEM ammon	ate data othe			
11. Did the incident result in exce	ess emissions?	No 🏈 Yes (Complete t	he following and attach of	alculations.)			
☐ voc	lbs 🗵	NOx 96.000	lbs SOx _		fbs	☐ H2S	lbs
□ co	lbs 🔲	PM	fbs 🔲 Other:		lbs		pollutant
2. For RECLAIM facilities Subjec	t to Rule 2004 (I)(3)	ONLY: If excess emissions					
when determining compliance	with your annual a	flocations?		,			
a. C Yes, for: NOx	□sox b.	. ⊂ No, for: □ NOx □	SOv				
If box 12(b) above is checked, in		specified in Rule 2004(i)(3)(B)	and (C), as applicable.				
3. Describe the steps taken to co	rrect the problem (i	specified in Rule 2004(i)(3)(B)	and (C), as applicable.	ment repairs, et	c.) and the pre	ventative measures o	employed to
 Describe the steps taken to co avoid future incidents, include 	rrect the problem (i photos of the failed	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and	and (C), as applicable. cess amissions, equipaltach additional pages	as necessary.			
Describe the steps taken to co avoid future incidents, include Increased the ammonia	rrect the problem (i photos of the failed I flow to bring d	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39	and (C), as applicable. cess amissions, equipaltach additional pages	as necessary.			
 Describe the steps taken to co avoid future incidents, include 	rrect the problem (i photos of the failed I flow to bring d Immonia scrubt	specified in Rule 2004(i)(3)(8) e., steps taken to mitigate e. d equipment if available and own the NOx ppm #39 per.	and (C), as applicable. cess amissions, equipaltach additional pages	as necessary.			
 Describe the steps taken to co avoid future incidents, include Increased the ammonia out the O rings on the a 	rrect the problem (i photos of the failed I flow to bring d Immonia scrubb erly prior to the Inc	specified in Rule 2004(i)(3)(8) e., steps taken to mitigate e. d equipment if available and own the NOx ppm #39 per.	and (C), as applicable. cess amissions, equipaltach additional pages	as necessary.			
3. Describe the steps taken to co avoid future incidents, include Increased the ammonia out the O rings on the at Was the facility operating prop a. Yes b. No,	rrect the problem (i photos of the failed the flow to bring d ammonia scrubt erly prior to the inci- because:	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident?	and (C), as applicable. ccess amissions, equip attach additional page: 6 O2 number until	s as necessary. repairs could			
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at Was the facility operating prop a. Yes b. No.	rrect the problem (i photos of the failed t flow to bring d immonia scrubb erly prior to the inci- because: erator error, neglect	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 oer. ident? t or improper operation or m	and (C), as applicable, coss amissions, equipattach additional pages 6 O2 number until	s as necessary. repairs could			
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at Was the facility operating prop a. 4. Yes b. No, i. Did the incident result from operating of the incident result from operating prop b. Yes b. No,	rrect the problem (in photos of the failed a flow to bring diammonia scrubt erly prior to the incipecause: erator error, neglect because: Stack	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident?	and (C), as applicable, coss amissions, equipattach additional pages 6 O2 number until	s as necessary. repairs could			
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at Was the facility operating prop a. Yes b. No, i. Did the incident result from operating of the incident result from operating the incident resul	rrect the problem (in photos of the failed a flow to bring diammonia scrubt erly prior to the incipecause: erator error, neglect because: Stack	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 oer. ident? t or improper operation or m	and (C), as applicable, coss amissions, equipattach additional pages 6 O2 number until	s as necessary. repairs could			
3. Describe the steps taken to co avoid future incidents, include Increased the ammonia out the O rings on the a 4. Was the facility operating prop a. Yes b. No, i. Did the incident result from ope a. Yes b. No, 4. Has the facility returned to com a. No, because:	rrect the problem (is photos of the failed a flow to bring dummonia scrubberly prior to the incibecause: erator error, neglect because: Stack apliance?	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #3% per. ident? t or improper operation or m flow indication was	and (C), as applicable, coss amissions, equipaltach additional pages 6 O2 number until	s as necessary. repairs could			
3. Describe the steps taken to co avoid future incidents, include Increased the ammonia out the O rings on the at the Ammonia out the O rings on the at the facility operating prop a. Yes b. No, i. Did the incident result from ope a. Yes b. No, i. Has the facility returned to com a. No, because: b. Yes (Attach evidence suctors)	rrect the problem (is photos of the failed in photos of the failed in photos of the failed in photos of the factorial in photos of the failed in ph	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #3% per. ident? t or improper operation or m flow indication was	and (C), as applicable, coss amissions, equipaltach additional pages 6 O2 number until	s as necessary. repairs could			
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at the County operating propa. Yes b. No. So. Did the incident result from operating the incident result from operating propa. Yes b. No. So. Has the facility returned to coma. No. because: b. Yes (Attach evidence sucted to continuous incidence sucted to conti	rrect the problem (in photos of the failed in photos o	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was	and (C), as applicable, coss amissions, equipaltach additional page: 6 O2 number until sintenance procedures wrong	repairs could	d be made.	Called in tech ch	nange
3. Describe the steps taken to co avoid future incidents, include Increased the ammonia out the O rings on the at the Ammonia out the O rings on the at the facility operating prop a. Yes b. No, i. Did the incident result from ope a. Yes b. No, i. Has the facility returned to com a. No, because: b. Yes (Attach evidence suctors)	rrect the problem (in photos of the failed in photos of the failed in photos of the failed in photos of the facility prior to the facility prior to the facility prior to the facility photos of the failed in photos of t	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was	and (C), as applicable, coss amissions, equipaltach additional page: 6 O2 number until sintenance procedures wrong	repairs could	d be made.	Called in tech ch	nange
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at the Incident result from operation of Incident result from operation of Incident results are true, accurate at the Incidents of Incidents	rrect the problem (is photos of the failed a flow to bring dummonia scrubberly prior to the incibecause: erator error, neglect because: Stack apliance? The as emissions calculatement sed on information te, and complete.	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was	and (C), as applicable, coss emissions, equipaltach additional pages 6 O2 number until sintenance procedures wrong	repairs could 7 ble evidence.)	d be made.	Called in tech of	attachments
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at the Incident result from operation of Incident result from operation of Incident results are true, accurate at the Incidents of Incidents	rrect the problem (in photos of the failed in photos of the failed in photos of the failed in photos of the incipation o	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was a lations, contemporaneous ope	and (C), as applicable, coss emissions, equipaltach additional pages 6 O2 number until sintenance procedures wrong	repairs could repairs and info for this facility as	d be made.	Called in tech of	attachments
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at the Incident result from operating properation of the Incident result from operation of the Incident result from Its operation of the Incident results of the Incident	rrect the problem (in photos of the failed in photos of the failed in flow to bring diammonia scrubble erly prior to the incibecause: Because: Because: Stack In as emissions calculatement Sed on information to, and complete. Belso certify under present and services of the complete.	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was a lations, contemporaneous ope and belief formed after reasonerably of law that that I am the	and (C), as applicable, coss amissions, equipaltach additional page: 6 O2 number until sintenance procedures wrong atting logs or other creditionable inquiry, the states responsible official in	repairs could repairs and info or this facility as	d be made.	Called in tech of document and in all MD Regulation XXX.	attachments
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at the Incident result from operating properation of the Incident result from operation of the Incident result from Its operation of the Incident results of the Incident	rrect the problem (in photos of the failed in photos of the failed in photos of the failed in photos of the incipation o	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was a lations, contemporaneous ope and belief formed after reasonerably of law that that I am the	and (C), as applicable, coss emissions, equipaltach additional pages 6 O2 number until sintenance procedures wrong atting logs or other creditional inquiry, the state responsible official to 2. Title of Responsible	repairs could repairs and info or this facility as	d be made.	Called in tech of document and in all MD Regulation XXX.	attachments
B. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the a out the O rings on the a was the facility operating prop a. Yes b. No, Did the incident result from operating of the incident result from operating prop a. Yes b. No, Has the facility returned to comerating the facility returned to comerating the incident evidence such that the incident evidence such that the incident evidence such that the incident materials are true, accurate the incident evidence of the incident evidence such that the incident evidence is the incident evidence and the incident evidence is the incident evidence and the incident evidence	rrect the problem (in photos of the failed in photos of the facility prior to the facility prior to the facility photos of the facilit	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was a lations, contemporaneous ope and belief formed after reasonerably of law that that I am the	and (C), as applicable, coss amissions, equipaltach additional page: 6 O2 number until sintenance procedures wrong atting logs or other creditionable inquiry, the states responsible official in	repairs could repairs could repairs and info or this facility as als Official:	mation in this defined in AC	Called in tech of document and in all MD Regulation XXX.	attachments
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at the O rings on the at the O rings on the at the facility operating prop a. Yes b. No, of the incident result from operating prop a. Yes b. No, the facility returned to come a. No, because: b. Yes (Attach evidence such at the facility returned to come at the facility returned to co	rrect the problem (in photos of the failed in photos of the failed in flow to bring diammonia scrubble erly prior to the incibecause: Because: Because: Stack In as emissions calculatement Sed on information to, and complete. Belso certify under present and services of the complete.	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was a lations, contemporaneous ope and belief formed after reasonerably of law that that I am the	and (C), as applicable, coss emissions, equipaltach additional pages 6 O2 number until sintenance procedures wrong rating logs or other creditionable inquiry, the state responsible official in 2. Title of Responsible 4. Date:	repairs could repairs could repairs and info or this facility as als Official:	d be made.	Called in tech of document and in all MD Regulation XXX.	attachments
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the a out the facility operating prop a. Yes b. No, Did the incident result from operating of the incident of the output of the incident of the i	rrect the problem (in photos of the failed in photos of the failed in flow to bring diammonia scrubble erly prior to the incibecause: Because: Stack inpliance? In as emissions calculatement sed on information to, and complete. Belso certify under prior to the incibecause: Stack in information to the incibecause in information to the incibecau	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was a lations, contemporaneous ope and belief formed after reasonerably of law that that I am the	and (C), as applicable, coss emissions, equipaltach additional pages 6 O2 number until sintenance procedures wrong atting logs or other creditional inquiry, the state responsible official to 2. Title of Responsible	repairs could repairs could repairs and info or this facility as als Official:	mation in this defined in AC	Called in tech of document and in all MD Regulation XXX.	attachments
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at the facility operating prop a. Yes b. No, is. Did the incident result from operating of the incident result from the incident res	rrect the problem (in photos of the failed in photos of the facility prior to the facility prior to the facility photos of the facilit	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was a lations, contemporaneous ope and belief formed after reasonerably of law that that I am the	and (C), as applicable, coss emissions, equipaltach additional pages 6 O2 number until sintenance procedures wrong rating logs or other creditionable inquiry, the state responsible official in 2. Title of Responsible 4. Date:	repairs could repairs could repairs and info or this facility as als Official:	mation in this defined in AC	Called in tech of document and in all MD Regulation XXX.	attachments
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at the Incident result from operating properating properating properating properating properating properating of the Incident result from operating of the Incident result from operating of the Incident result from operating of the Incident result from O results of the Incident results of the Incident results of the Incident results of Incident r	rrect the problem (in photos of the failed in photos of the failed in flow to bring diammonia scrubble erly prior to the incibecause: Because: Stack in pliance? In as emissions calculatement sed on information to and complete. Palso certify under prior to the prior to the incibecause: Stack in pliance?	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was lations, contemporaneous ope and belief formed after reasonenaity of law that that I am the	and (C), as applicable, coss emissions, equipaltach additional pages 6 O2 number until sintenance procedures wrong rating logs or other creditionable inquiry, the state responsible official in 2. Title of Responsible 4. Date:	repairs could repairs could repairs and info or this facility as als Official:	mation in this defined in AC	Called in tech of document and in all MD Regulation XXX.	attachments
3. Describe the steps taken to co avoid future incidents. Include Increased the ammonia out the O rings on the at the Incident result from operating properating properating properating properating properating properating of the Incident result from operating of the Incident result from operating of the Incident result from operating of the Incident result from O results of the Incident results of the Incident results of the Incident results of Incident r	rrect the problem (in photos of the failed in photos of the failed in flow to bring diammonia scrubble erly prior to the incibecause: Because: Stack inpliance? In as emissions calculatement sed on information to, and complete. Belso certify under prior to the incibecause: Stack in information to the incibecause in information to the incibecau	specified in Rule 2004(i)(3)(B) .e., steps taken to mitigate e d equipment if available and own the NOx ppm #39 per. ident? t or improper operation or m flow indication was lations, contemporaneous ope and belief formed after reasonenaity of law that that I am the	and (C), as applicable. coss amissions, equipaltach additional pages 6 O2 number until sintenance procedures wrong rating logs or other credi conable inquiry, the statue responsible official in the statue of Responsible of Respon	repairs could repairs could repairs could repairs and info or this facility as als Official: Pia	rmation in this defined in AC	Called in tech of document and in all MD Regulation XXX.	attachments

Colmac Energy
Mecca, CA
Boiler 1 Daily Emissions Report
September 10, 2022

	Process	Status	Startup	Startup	Startup	Startup	Startup	Normal	Normal	Normal	Normal	Normal	Normal	Normai	Normal	Normal	Normal	Normat	Normai	Normal	Normal	Normal	Normal	Normal	Normal	Normal Normal	(volution	•••••	
	° (COlbs	3,12	3.02	2.92	2.83	2.65	2.53	2.52	3.59	3.90	4.09	3.57	3.65	3.66	3.69	3.71	3.72	3.78	3.81	3.85	3.89	3.90	3.84	e e) 0 0 0 0		84.0	
	00	mannin	0.014	0.015	0.016	0.016	0.018	0.018	0.021	0.015	0.013	0.012	0.013	0.013	0.013	0.013	0.012	0.012	0.013	0.013	0.013	0.013	0.013	0.013	0.013	0.013	0.044	r S	0.01 *
	CO ppm	70 00 00	(6,9 (9,0	17.9		7 * 6	2, 5	24.9	24.0 C 1	1.71	14.9	14.3	14.9	14.8	14.8	14.9	14.7	14.7	14.8	14.8	14.8	14.8	14.9	14.8	14.8	14.8	16.5		* *
2*-310 -0.46	CO ppm		0.01	D, C	20.0	10.0t	10.0	2 0	0,00	0,0	0.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.01	10.0	10.0	10.0		
tolling Btu - 0.3 CO ppm @3% O2 * - 310 CO lb/mmBtu * - 0.46	SO2 lbs	9 52	0.00 0.00 0.00 0.00	7.53	6.74	6.11	3.34	(e)	0000	, 4 , 6 , 6	4.00	֓֞֞֞֞֞֞֞֞֞֞֓֓֓֞֞֞֓֓֓֓֞֞֓֓֓֓֓֞֞֞֞֓֓֓֓֓֓֞֟֓֓֓֓֞֓֞֓֞֓֓֓֞֡֞֞֓֡֓֞	4.17	4.62	4./4	4.91	4.76	4.75	4.67	4.92	0. 10 0. 10	0 1 0 1	7.37	8.64	7.46	7.08	***************************************	132.93	55971
ifts 30-Day F 10x Ib/mm 2-23.3 -1.2 SO2	SO2 lb/mmBtu	0.039	0.034	0.040	0.039	0.041	0.026	0.028	0.028	0.015	200	Cai	0.03	0.0.0	0,0,0	20.0	0.010	0.015	0.016	0,010	200	0.012	0.024	0.028	0.024	0.023	0.024	7600	
	SOZ ppm @3% OZ	20.1	17.7	20.9	20.2	21.3	13.3	14.2	14.4	7.9	~ C	8.7	ξα	- x	4 1 0 č	· r	a A c	7.0) a	1 1 0 (, G	0.00	1 5 F	n (12.4	11.8	12.4	24.0)
SO2 pg	SO2 ppm	11.9	9,9	11,3	10.5	10.1	5,8	5.8	Б.	5.3	Ca	ry ex		5.7	. cc	5.5	i Ki) K	5.7	. o) C	i o	80) t	Q (8 0	7,4		
Daily NOx lbs- 648	NOx lbs	24.75	23.74	25.88	25.01	13.68	7.68	7.80	21.23	14.84	23.06	16,14	16.82	16.17	21.84	25.50	23,27	23,80	23,31	23.40	24,23	24,33	25.35	23.40	P C	48.07	804.20	20170	
ON	NOx Ib/mmBtu	0.114	0.120	0.139	0.145	0.092	0.059	0.065	0.089	0.048	0.068	0.057	0.058	0.056	0.075	0.086	0.078	0.079	0.077	0.076	0.078	0.079	0.083	0.076	2000	0,004	0.083	0.087	
	NOx ppm @3% 02	81.6	85.7	9 9 9 9	103.7	7.00	4 4 U 0	40.3	63,4	34.6	48.4	41.0	41.6	39.8	53.7	61.3	55.8	2.99	55.2	54.6	56.1	56.7	59.5	54.4	£0.4	, oo, e	59.1		
	MQx DDM	48.3	2	0, 6, 6, 6, 6, 6, 6, 6, 6, 6, 6, 6, 6, 6,	2, 2, 2, 2, 2	, c	, 2 , 2 , 2, 2	2. 0. 0. 0. 0. 0.	0.00 0.00	23,2	33.8	27.5	28.1	26.9	36.0	41.8	38.0	38.3	37.3	36.9	37.9	38.0	40.2	36.8	40,6	***************************************	36.2		
	02%	5 5 0 0	, , , , , , , , , , , , , , , , , , ,	- - -	12.4	<u>.</u>	13.6	10.8	o, a	ņ 6	φ, q	න න	හ.	න. හි	80	8.7	8.7	8,8	හ හ	8.8 8.	8.8	ر ش ن	8.8	8.8	8,8	University of the Control of the Con	တ		
•	Hour	3 5	. 60	8 8	40	05	90	0.7	80	? 6	0 4	2 ;	- (7 5	<u>n</u> ;	4	ည	ည်း မ	>	\$	6	20	N	22	23	***************************************	Average Total	30-Day Ring	n.

^{*- 720} hour average of the previous 720 valid hours, excluding startup/shutdown

CeDAR Reports 9/13/2022 6:30 AM, Boiler 1 Daily Emissions Report

Boiler 1 Excess Emissions Colmac Energy NOx ppm @3% 02 3-Hr Boiling Excess

	Action			
2022	Limit Reason	False Stack flow	reading	***************************************
missions for 9/10/	Мах	96.0		
Rolling Excess E		96.0		
NOA PULL (#3% UZ 3-Hr Rolling Excess Emissions for 9/10/2022	End Duration	JNOU I IND CO.CO.	AAN	1 hour
Parameter	m @3% O2 3-Hr 9/10/2022 3:00 AM		Total Auration	יסימן שטימוויטן: